ANSYS Class3 Error Report

ERROR NO:

2014-08

Keywords:

ELBOW290   SECOFFSET

Description of Error:

When no orientation node is used for the ELBOW290 element, the
section offset (input on the SECOFFSET command) is processed in the
wrong direction.

Typical GUI Path(s):

Main Menu>Preprocessor>Sections>Pipe>Add

Other Comments:

First Incorrect Version:

Release 12.0

Corrected In:

Release 16.0

Suggested User Action For Running on Uncorrected Version:

If using the SECOFFSET command, use an orientation node to define
the element coordinate system.

Author Signature:
 Wenjie Xie 4/21/2014

Reviewed By QA:
 Bill Bryan 4/21/2014

Approval:
 Dave Conover 4/21/2014