

ANSYS Class3 Error Report**ERROR NO:**

2013-22

Keywords:

PIPE288 PIPE289 LINEAR PERTURBATION PRESSURE LOADING

Description of Error:

The hoop and radial stresses in the wall caused by pressure loading are not recovered during linear perturbation modal or eigenvalue buckling analyses. The axial and transverse shear stresses are correctly handled.

Typical GUI Path(s):

Main Menu>Solution>Analysis Type>Restart

Other Comments:**First Incorrect Version:**

Release 14.5

Corrected In:

Release 15.0

Suggested User Action For Running on Uncorrected Version:

Author Signature:

Wenjie Xie 9/26/2013

Reviewed By QA:

Bill Bryan 10/3/2013

Approval:

Dave Conover 9/26/2013