ANSYS Workbench Class3
Error Report
ERROR NO:
WB2012-02
Keywords:
RESULTS ENERGY PROBES RIGID DYNAMICS
Description of Error:
In a rigid body dynamics analysis, energy probes scoped on a body give incorrect results when model has contacts.
Typical GUI Path(s):
Other Comments:
All other results are unaffected by this problem.
First Incorrect Version:
Release 13.0
Corrected In:
Release 14.5

Suggested User Action For Running on Uncorrected Version:

Energy can be checked by scoping energy probes on the system.

Author Signature:

Stephane Garreau 2/10/2012

Reviewed By QA:

Bill Bryan 2/17/2012

Approval:

Dave Conover 2/10/2012