

ANSYS Workbench Class3**Error Report**

ERROR NO:
WB2013-11

Keywords:

MULTIZONE MESHING

Description of Error:

If a MultiZone meshing method fails to mesh correctly, the solve button will not be disabled allowing the user to solve using an incomplete mesh leading to incorrect results.

Typical GUI Path(s):

Select Mesh on the Tree Outline, right-click to view the menu, and select Insert>Method MultiZone

Other Comments:**First Incorrect Version:**

Release 14.0

Corrected In:

Release 15.0

Suggested User Action For Running on Uncorrected Version:

Users should double-check to ensure that the surface mesh covers all faces before they do a calculation.

Author Signature:

Andreas Kolms 5/2/2013

Reviewed By QA:

Bill Bryan 5/14/2013

Approval:

Dave Conover 5/6/2013