

ANSYS Workbench Class3**Error Report****ERROR NO:**

WB2014-09

Keywords:

PIPE SECTION OFFSET

Description of Error:

User-defined offsets for pipe sections are incorrectly defined in the solver input file. The SECOFFSET command is written in a wrong format resulting in the offsets being interpreted incorrectly.

Typical GUI Path(s):

1. Import a line body and set the 'Model Type' to 'Pipe'.
2. Change Offset Type to 'User Defined'.
3. Enter values for 'Offset X' and/or 'Offset Y'.
4. Apply structural loads and solve.

Other Comments:**First Incorrect Version:**

Release 14.0

Corrected In:

Release 16.0

Suggested User Action For Running on Uncorrected Version:

None

Author Signature:

Deepak Garg 6/10/2014

Reviewed By QA:

Bill Bryan 6/16/2014

Approval:

Dave Conover 6/10/2014