

ANSYS Workbench Class3**Error Report****ERROR NO:**

WB2015-03

Keywords:

BEAM CONNECTIONS

NONLINEAR MATERIAL

Description of Error:

Nonlinear material properties assigned to beam connections in Mechanical are not sent to the solver and therefore ignored during the solution process.

Typical GUI Path(s):

Insert a Beam Connection object and assign it a nonlinear material

Other Comments:**First Incorrect Version:**

Release 16.0

Corrected In:

Release 16.1

Suggested User Action For Running on Uncorrected Version:

Author Signature:

Mohamed Koubaa 2/24/2015

Reviewed By QA:

Bill Bryan 2/25/2015

Approval:

Dave Conover 2/24/2015